



Its very common for the teeth on the original window regulators to be worn down

We have found that they
sometimes cause the
regulator to run past the stop
meaning the glass drops down
into the door and wont
come up using the switch



A useful fix is to weld a lug onto the end of the toothed arm, this stops the arm riding past the stop when its at the lowest point

Heres the result after welding